

Important Notice About Replacing the TippingPoint CFast Card

IMPORTANT: Failure to properly remove the TippingPoint CFast card can result in disk corruption and a system error.

You can replace the CFast card when the system is operating. Before you remove the card, use the command line interface (CLI) to **first unmount the card**. For the appropriate unmount command, consult your product hardware installation or CLI documentation on the Trend Micro Online Help Center at:

https://docs.trendmicro.com/en-us/documentation/

After you successfully unmount the previous storage card, you can insert a new card into the CFast slot. Issue the appropriate mounting and preparation commands in the CLI.

When you manually mount and format a CFast card, the card will mount automatically when the appliance boots.

Legal and notice information

© 2016 Trend Micro Incorporated. All rights reserved.

Trend Micro makes no warranty of any kind with regard to this material, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Trend Micro shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance, or use of this material.

This document contains proprietary information, which is protected by copyright. No part of this document may be photocopied, reproduced, or translated into another language without the prior written consent of Trend Micro. The information is provided "as is" without warranty of any kind and is subject to change without notice. The only warranties for Trend Micro products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. Trend Micro shall not be liable for technical or editorial errors or omissions contained herein.

TippingPoint[®], the TippingPoint logo, and Digital Vaccine[®] are registered trademarks of Trend Micro All other company and product names may be trademarks of their respective holders. All rights reserved. This document contains confidential information, trade secrets or both, which are the property of Trend Micro No part of this documentation may be reproduced in any form or by any means or used to make any derivative work (such as translation, transformation, or adaptation) without written permission from Trend Micro or one of its subsidiaries.

Important Notice About Replacing the TippingPoint CFast Card

Publication Part Number: 5200-1084, Rev A1